


Time-Dependence




Monday,
Oct. 12, 2003

MATS275: INTRODUCTION
TO MATERIALS SCIENCE

- Phases - Recap
- Nucleation and Growth
- The Avrami Relationship
- Diffusionless Transformations
- Quenching of Irons
- Phases and Microstructures
 - Cementite, Ferrite, Pearlite, Bainite, Martensite, and Spheroidite
- Hardenability
- Alloying of Steel

The Next Dimension : Time

- No phase transformation occurs instantly.
 - Nucleation
 - Homogeneous
 - Heterogeneous
 - Growth



Homogeneous Nucleation

- Surface must form between phases
- Surfaces have high energy
- Energy gained by phase change must offset this

Related to volume

Related to surface area

Free Energy Released by Phase Change

$$\Delta G_n = 4\pi r^2 \gamma + \frac{4}{3}\pi r^3 (\Delta G_v)$$

Free energy/area of surface

Nucleation Energy

The Critical Radius

- Smaller than r^* and particles redissolve,
larger than r^* and they grow on and on...

$$\frac{d}{dr}(\Delta G_n) = 8\pi r\gamma + 4\pi r^2(\Delta G_v)$$

$$8\pi r^*\gamma + 4\pi r^{*2}(\Delta G_v) = 0$$

$$r^* = \frac{-2\gamma}{\Delta G_v}$$

The Effect of Temperature

- Remember what the Gibb's Free Energy is...

$$\Delta G_v = \Delta H_v - T\Delta S$$

At equilibrium $\Delta G_v = \Delta H_v - T_E\Delta S = 0$

$$\Delta S = \frac{\Delta H_v}{T_E}$$

$$\Delta G_v = \Delta H_v - T_E \frac{\Delta H_v}{T_E} = \Delta H_v \frac{T - T_E}{T_E}$$


$$\Delta G_v = \left(\frac{\Delta H_v}{T_E} \right) \Delta T$$

The Effect of Temperature

$$r^* = \frac{-2\gamma}{\Delta G_v} = \frac{-2\gamma T_E}{\Delta H \Delta T} \quad \Delta G_n = 4\pi r^2\gamma + \frac{4}{3}\pi r^3(\Delta G_v)$$


$$\begin{aligned} \Delta G_n &= 4\pi \left(\frac{-2\gamma T_E}{\Delta H \Delta T} \right)^2 \gamma + \frac{4}{3}\pi \left(\frac{-2\gamma T_E}{\Delta H \Delta T} \right)^3 \left(\frac{\Delta H}{T_E} \Delta T \right) \\ &= \frac{16\pi\gamma^3 T_E^2}{3\Delta H^2} \left(\frac{1}{\Delta T} \right)^2 \end{aligned}$$

Free Energy Change vs. r



Competing Mechanisms

- But there is also the need to diffuse...



Nucleation Mechanisms

- Homogeneous
- Heterogeneous
 - Coherent (lattice match across interface)
 - Semicohherent
 - Incoherent

Growth

- Growth proceeds from nucleation.
- Avrami relation...

$$X = 1 - e^{-(kt)^n}$$

Fraction transformed

$0.5 < n < 5.0$ typ.

k is a rate constant

The Transformation Rate

$$r = \frac{1}{t_{1/2}}$$


At a given temperature

Temperature dependence

$$r = Ae^{-Q/RT}$$

Q - Activation Energy
 T - Absolute Temperature
 R - Gas Constant
 A - Pre-exponential Constant

TEMPERATURE DEPENDENCE



Crystallization of Cu

- At 900°C, the growth rate of Cu is 10^6 times as large as at 400°C. What is the activation energy?

$$\frac{G_{900}}{G_{400}} = \frac{Ae^{-Q/R(1173\text{ K})}}{Ae^{-Q/R(673\text{ K})}} = e^{-\frac{Q}{R}\left(\frac{1}{1173} - \frac{1}{673}\right)}$$


$$\ln(10^6) = -\frac{Q}{R}\left(\frac{1}{1173} - \frac{1}{673}\right)$$

$$13.8 = -\frac{Q}{8.314 \frac{\text{J}}{\text{mol}\cdot\text{K}}}\left(6.33 \times 10^{-4}\right)$$

$$Q = 181 \frac{\text{kJ}}{\text{mol}}$$


Competing Mechanisms

solidification



Flipping the Rate


- The inverse of the rate is the time it takes for the reaction to complete...



Types of Transformations

- Diffusional
 - solidification, recrystallization, grain growth
 - eutectic (change of phase composition)
- Diffusionless
 - Martensitic


Fe-Fe₃C Phase Diagram




- α** - Ferrite - BCC iron
- β** - high temperature BCC iron
- γ** - Austenite - FCC iron
- Fe₃C** - Cementite or Carbide

Slow Cooling

- Slow cool
- Cool and hold at 650°C
- Forms coarse pearlite.




Pearlite




Faster Cooling

- Moderate cool
- Cool and hold at 575°C
- Forms fine pearlite.





Even Faster Cooling

- Cool and hold at 300°C
- Forms Bainite.




Bainite




Martensitic Transformation

- Athermal, Diffusionless




Martensite



Martensitic Transformation

- Austenite to Martensite




How Much Are We Talking About?

- How many Carbon interstitials are we talking about in eutectoid steel (0.76 % C)?

$$\begin{aligned}
 0.0076 &= \frac{m_C}{m_C + m_F} = \frac{(12.001 \text{ u})n_C}{(12.001 \text{ u})n_C + (55.85 \text{ u})n_F} \\
 &= \frac{(12.001 \text{ u})}{(12.001 \text{ u}) + (55.85 \text{ u})\frac{n_F}{n_C}} \\
 \frac{n_F}{n_C} &= \frac{(12.001 \text{ u}) - (12.001 \text{ u})}{(55.85 \text{ u})} = 7.02
 \end{aligned}$$


Example

- Quench to 350°C
- Hold for 3 hrs
- Quench to RT



Example

- Quench to 650°C
- Hold for 20 s
- Quench to 400°C
- Hold 17 min
- Quench to RT



Example

- Quench to 250°C
- Hold for 2 min.
- Quench to RT

