


Metals




Wednesday,
Oct. 15, 2003

MATS275: INTRODUCTION
TO MATERIALS SCIENCE


- Annealing Steels
- How Steel is Made
- Alloy Steels
- Stainless Steel
- Non-Ferrous Metals
 - Aluminum
 - Magnesium
 - Titanium
 - Copper
 - Nickel
 - Others

Hypereutectoid Steel




1.13 % C

Hypoeutectoid Steel



0.5 % C

4340 Alloy Steel



Rules of Thumb


- Cementite
 - hard but brittle
- Martensite
 - hard but brittle
- Ferrite
 - ductile and soft - machinable

Characteristics of Phases


- Pearlite
 - ferrite mixed with cementite - makes it hard
- Fine Pearlite
 - even harder and stronger
 - grain boundary adhesion
 - grain size strengthening
- Spheroidite
 - hard & strong because of small grains, but also ductile

Pearlite

Effect of Carbon Content




Pearlite & Spheroidite



Characteristics of Phases


- Martensite
 - hardest and strongest
 - alloy effects (rather than grain size)
 - few slip directions in BCT
 - most brittle - almost unusable
 - quenching can lead to cracking
 - swelling due to BCT

Martensite




TEMPERING

- Martensite converts to small grains of cementite in ferrite - help to reinforce it.




TEMPERING

- Martensite converts to small grains of cementite in ferrite - help to reinforce it.
- Spheroidite
- Thermal stresses on quench can cause cracking.




MARTEMPERING

- Hold just above Martensite temperature to equilibrate



MARTEMPERING

- Hold just above Martensite temperature to equilibrate



Annealing

- Process Anneal
 - removes effects of work-hardening, restores ductility*
 - Stress Relief
 - Normalizing
- Full Anneal

Iron & Steel

- 2.0 - 4.5 wt % C = Cast Irons
- 0.05 - 2.0 wt % C = Steel
 - >5 wt % other elements = high-alloy steel
 - <5 wt % other elements = low-alloy steels
- >90 wt % of the metallic materials used by humans are ferrous alloys

$\rho = 7.87 \text{ g/cc}$, BCC, $T_m = 1538^\circ\text{C}$

How To Get Steel

- Coke + iron ore into blast furnace.
 - Reduction Rxn $\text{Fe}_2\text{O}_3 + 3\text{CO} \rightarrow 2\text{Fe} + 3\text{CO}_2$
- Pig iron transferred to oxygen furnace.
 - $\text{FeO} + \text{C} \rightarrow \text{Fe} + \text{CO}$
 - Before reaction starts, lime is added as a flux
 - Alloying elements added

Why Alloys?

- Plain carbon steels cannot be strengthened past 100,000 psi without a substantial loss in ductility and impact resistance.
- Large area pieces of plain carbon steel are subject to temperature gradients - non-uniform martensite formation.
- Plain carbon steels are more easily oxidized and corroded.
- Plain carbon steels are less impact resistant at low temperatures.
- Some plain carbon steels must be quenched so rapidly that warping and/or cracking become a problem.

What Alloys?

AISI#	Elements	AISI#	Elements
13xx	Mn	5xxx	Cr
40xx	Mo or Mo & S	61xx	Cr, V
41xx	Cr, Mo	86xx	Ni, Cr, Mo
43xx	Ni, Cr, Mo	87xx	Ni, Cr, Mo
44xx	Mo	88xx	Ni, Cr, Mo
46xx	Ni, Mo	92xx	Si or Si & Cr
47xx	Ni, Cr, Mo		
48xx	Ni, Mo		

AISI = American Iron and Steel Institute
SAE = Society of Automotive Engineers

What Alloys Do

	Dissolve in Ferrite	Dissolve in Carbide	Form Carbide	Form Compound
Ni	○			
Si	○			$\text{SiO}_2 \cdot \text{M}_x\text{O}_y$
Mn	○ ← ○		$(\text{Fe, Mn})_3\text{C}$	$\text{MnS, MnO} \cdot \text{SiO}_2$
Cr	○ ← ○		$(\text{Fe, Cr})_3\text{C}$	
Mo	○ ← ○	○ →	Mo_2C	
W	○ ← ○	○ →	W_2C	
V	○ →	○ →	V_4C_3	
Ti	○ →	○ →	TiC	

Other Treatments of Steels

- Carburizing and Nitriding
 - anneal in CH_4 , CO, or CO_2
 - anneal in NH_3
- Case Hardening
 - flame heat outside to form Martensite

form areas that are susceptible to fatigue and wear but not necessarily shock

Stainless Steels

- ALL have at least 12% Cr
- Ferritic - up to 30% Cr, <0.12% C
 - low cost, good strength ...structural uses
- Martensitic - 12-17% Cr, 0.15-1.0 % C
 - hard, resists corrosion ... knives, bearings, etc.
- Austenitic - <0.03% C, 7 - 20% Ni
 - resists corrosion, non-magnetic, expensive

Aluminum Alloys

- Formed by Hall-Herault process
 - electrolytic reduction of Al_2O_3
- Abundant and inexpensive
- Light Weight
- Corrosion Resistant
- Non-Toxic

$\rho = 2.71 \text{ g/cc}$, FCC, $T_m = 660.4^\circ\text{C}$

Magnesium Alloys

- Extracted from Chlorides in Sea Water
- Very Reactive With Air
- More Expensive Than Al
- Light Weight
- hcp So Not Very Ductile

$\rho = 1.74 \text{ g/cc}$, HCP, $T_m = 649^\circ\text{C}$

Titanium Alloys

- Separated at High Temperature From Ore
- Very Expensive
- Corrosion Resistant (TiO_2)
- Light Weight
- hcp up to 882°C then bcc
- Embrittled by Light Elements at High Temp

$\rho = 4.51 \text{ g/cc}$, HCP, $T_m = 1668^\circ\text{C}$

Copper Alloys

- Separated From Ore by Melting
 - slag drained off
- Highly Conductive
- Ductile
- Alloys
 - Cu-Zn = Brass
 - Cu-Sn = Bronze
 - Cu-Be = spring copper

$\rho = 8.94 \text{ g/cc}$, FCC, $T_m = 1084^\circ\text{C}$

Nickel Alloys

- Derived from ore
- Used in High T Alloys
 - Monel = Ni/Cu
 - Inconel = Ni/Cr/Fe
 - Hastelloy = Ni/Mo/Fe/Cr
 - Superalloy = Ni/Al
- Corrosion Resistant

$\rho = 8.90 \text{ g/cc}$, FCC, $T_m = 1453^\circ\text{C}$

Zinc, Lead, and Others

- Zinc
 - Galvanization
- Lead
- Refractory Metals
 - Mo, Rh, Ta, W
- Precious Metals
 - Au, Ag, Pd, Pt
